



Preliminary Information

PIT5774 Overhead Roof Console Inoperative / Service Safety Restraints Message / Sunroof Inoperative / Dome Lights Inoperative / DTCs B1A7A and U1121

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Tahoe	2021	All	All	All	All
Chevrolet	Suburban	2021	All	All	All	All
GMC	Yukon Models	2021	All	All	All	All

Involved Region or Country	North America
Condition	<p>Some customers may comment on the following complaints:</p> <ul style="list-style-type: none"> - Service Safety Restraints System Message - Sunroof Inoperative - Sunshade Lights Inoperative - Dome Lights Inoperative - Power Liftgate Inoperative when using switch in overhead console <p>When the vehicle is checked for DTC's there will be a current U1121 set in the BCM and B1A7A set in the Restraints Module.</p>
Cause	The cause of these concerns could be a logic lock with the A103 Roof Console.

Correction:

Engineering is currently working on releasing a fix. In the meantime, turn the ignition off and remove the F3DR fuse from the X51R Right IP fuse block for one minute. Reinstall the fuse, turn the ignition on and check to make sure the roof console features now operate, and verify that the DTC's are now history.

-If the vehicle is repaired, do not replace the A103 roof console for this concern. Engineering will be releasing a fix shortly and the PI will be updated at that time.

-If the vehicle is not repaired, then the information in this PI does not apply and normal SI diagnostics should be performed.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*1086268	Check DTC's and Overhead Console Function, Cycle F3DR, Clear DTC's	0.3 Hr

Labor Operation	Description	Labor Time
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	09/14/2020 - Created on.



GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.